



Describe the scene depicted in the image, focusing on the visibility of lane lines, presence of vehicles or obstacles, weather conditions, and any other relevant details. Don't give any scores.



The image shows a road scene with high illumination from the sun, which is positioned directly ahead, causing glare. A large truck is present, partially obstructing the lane lines. Some lane lines are visible, though they appear slightly unclear due to the sunlight and slight haziness in the image.



Rating blurred image during daytime: [Score 0-10] – Rate the overall image clarity/sharpness on a scale of 0-10, where 10 is extremely blurry/out of focus and 0 is tack sharp, with no visible blur.



The blurred image during daytime score is 2, indicating slight blur and haziness in the image.



Rating Lane Lines Invisibility due to Illumination (darkness or shadows): [Score 0-10] – Rate the invisibility of lane lines due to poor lighting conditions.



The lane lines invisibility score due to illumination is 7, indicating that the bright sunlight is significantly affecting the visibility of the lane lines.



Rating Vehicles or Other Objects Covering Lane Lines: [Score 0-10] – Rate if lane lines are covered by vehicles or objects.



The vehicles or other objects covering lane lines score is 3, indicating the truck is partially covering the lane lines.



Rating visibility of Lane Lines: [Score 0-10] – Rate the overall visibility of the lane markings.



The visibility of lane lines score is 3, as only some lane lines are visible since they are obscured by the vehicle and the glare from the sunlight.

Confidence Score = 0.4